### **ENVIRONMENTAL CHEMISTS**

## Analysis For Total Metals By EPA Method 200.8

Client ID: M122175

Date Received: 03/26/09

Date Extracted: 03/31/09

Date Analyzed: 04/01/09

Matrix: Water

Units: ug/L (ppb)

Client:
Project:
Lab ID:
Data File:
Instrument:

Alaskan Copper Works PO M122175, F&BI 903244

903244-01 x10 903244-01 x10.034

Instrument: ICPMS1 Operator: hr

Internal Standard: Germanium

% Recovery:

Lower Limit: 60 Upper Limit: 125

Concentration
ug/L (ppb)

Chromium
363
Nickel
416
Copper
383
Zinc
29.6

### **ENVIRONMENTAL CHEMISTS**

Client:

### Analysis For Total Metals By EPA Method 200.8

% Recovery:

<1

Client ID: Method Blank
Date Received: Not Applicable
Date Extracted: 03/31/09
Date Analyzed: 04/01/09
Matrix: Water
Units: ug/L (ppb)

Internal Standard:

Zinc

Project: PO M122175, F&BI 903244
Lab ID: I9-136 mb
Data File: I9-136 mb.024
Instrument: ICPMS1
Operator: hr

Lower

Limit:

60

Alaskan Copper Works

Upper

Limit:

125

Germanium 103

Concentration ug/L (ppb)

Chromium <1
Nickel <1
Copper <1

### **ENVIRONMENTAL CHEMISTS**

Date of Report: 04/08/09 Date Received: 03/26/09

Project: Metro Self Monitor, PO M122175, F&BI 903244

## QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 903234-01 (Duplicate)

Analyte	Reporting Units	Sample Result	Duplicate Result	Relative Percent Difference	Acceptance Criteria			
Chromium	ug/L (ppb)	3.15	2.94	7	0-20			
Nickel	ug/L (ppb)	1.72	1.56	10	0-20			
Copper	ug/L (ppb)	<1	<1	nm	0-20			
Zinc	ug/L (ppb)	3.92	1.68	80 a	0-20			

Laboratory Code: 903234-01 (Matrix Spike)

Analyte	Reporting Units	Spike Sample Recovery Reporting Units Level Result MS						
Chromium	ug/L (ppb)	20	3.15	105	50-150			
Nickel	ug/L (ppb)	20	1.72	99	50-150			
Copper	ug/L (ppb)	20	<1	102	50-150			
Zinc	ug/L (ppb)	50	3.92	92	50-150			

Laboratory Code: Laboratory Control Sample

Analyte	Reporting Units	Spike Level	Percent Recovery LCS	Acceptance Criteria				
Chromium	ug/L (ppb)	20	108	70-130				
Nickel	ug/L (ppb)	20	106	70-130				
Copper	ug/L (ppb)	20	105	70-130				
Zinc	ug/L (ppb)	50	99	70-130				

#### **ENVIRONMENTAL CHEMISTS**

## **Data Qualifiers & Definitions**

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

903244	AMPLE CHAIN OF CUSTODY ME	03/26/09 AI,
Send Report To Genera A. THOMOSON	re	Page #of
Company ALASKAN Coppen works  Address 628 S. Handel So	PROJECT NAMENO. PO METRO Self monder M/2:	# Standard (2 Weeks)  RUSH  Rush charges authorized by:

		ANALYSES REQUESTED															
Sample ID	Lab ID	Date	Time	Sample Type	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B		8270	HFS	272				.]	Notes
m 122175	01	3/24/09	11:80	HZO	)		4	4	4		1						
						v I	+	+	+	ł	-	+	╬-				
**************************************			t.				1		$\perp$	$\perp$							
													_				
				185 		+	+	+	4	-	+	+	-	$\vdash$			
						$\dashv$	+	+	+	+	-	+	-	H	-		
***************************************						+	$\dagger$	+	t	$\dagger$	+	╁	$\vdash$	1427			7. /** <del>**********************************</del>
	,	\$\$	5			1	1						1				
riedman & Bruya, Inc. 012 16th Avenue West	SIGNATURE Relinquicked by			PRINT NAME  (SEASU Thompsi				COMPANY				in	DATE 3		TIME 1:267		
eattle, WA 98119-2029 h. (206) 285-8282	Recrived by:  Relinquished by:			Khan Phan				FeB_I					3/20	2/09	4 4		
ax (206) 283-5044	Received by:				NO.							1		1			

#### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

April 8, 2009

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on March 26, 2009 from the Metro Self Monitor, PO M122175, F&BI 903244 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you should have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0408R.DOC

#### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

April 8, 2009



### **INVOICE #09ACU0408-1**

Accounts Payable Alaskan Copper Works 628 South Hanford Seattle, WA 98134

RE: Project Metro Self Monitor, PO M122175, F&BI 903244 - Results of testing requested by Gerry Thompson for material submitted on March 26, 2009.

federal tax id #(b) (6)